

24 Marchl 2012: platform moved to lake center, 12-1:00pm Nov11: Tightened electrical connections for Tw's in MUX box on 13Nov11 (most could be tightened 1/2 turn or more so this may have solved problem detected earlier)







See figure to right for actual de

Lake level is mm above lower edge of dock metal frame (mm of water at 4C based on pressure) 0.80 inches

Dock old deck upper surface (before replacement with new artificial wood decking) was at about +200 mm at SE corner but about +50-100mm at NW & NE corners)

Precip from rain gage is underestimated during freezing conditions and appears late when air temperature rises above freezing. Lake level rise accurately reflects rain or the water equivalent of snow, plus runoff and snowmelt.





					mm
		mm Precip,	mm Precip,		Precip,
	date	NWS	Lac	date	NWS
accuweather (Hamlin=Scranton)	1-Dec	0.00	0.10	9-Dec	1.02
rain or water-equiv snow, mm	2-Dec	1.02	1.00	10-Dec	6.60
	4-Dec	0.51	0.90	11-Dec	1.02
	5-Dec	6.35	2.50		
	7-Dec	4.32	5.50		
	8-Dec	4.06	4.50		

Precip, Lac	date	mm Precip, NWS
1.00		
3.90		
1.00		
-		
-		
-		

mm Precip, Lac	29Oct11 snow	.64" water equiv	from lake level, 0.3	2" water	equiv from de	layed rain ga	age & from	Hamlin/Hav	wley
-			-				24.9	Hamlin=S	cranton to
-			-		rain gage t	to date,mm	21.8	87%	lac/NWS,
-			-					102%	Lac/Haml
-			-		Mar	Apr	May	Jun	Jul
-			-	2012	73%	125%	78%	91%	1499
-			-	2011		77%	62%	95%	98%