


Statistical Process Control

- Is a tool for
 - achieving process stability
 - improving capability by reducing variability
- Variability can be due to
 - **chance causes** (relatively small)
 - **assignable causes** (generally large compared to background noise)

1



Control Charts



- $UCL = \mu_W + k\sigma_W$
- $CL = \mu_W$
- $LCL = \mu_W - k\sigma_W$

Types of Control Charts:

- Variables Control Charts
- Attributes Control Charts

2

Purpose of Control Charts

- Improving productivity
- Preventing defects
- Preventing unnecessary process adjustments
- Providing diagnostic information
- Providing information about process capability

3

Design of a Control Chart

- An \bar{X} control chart:
 - Standard deviation of the sample average.
 - Choosing the control limits.
- Relationship to hypothesis testing.
- Decisions:
 - Sample size to use.
 - Frequency of sampling.

4

Example of the control chart

- In manufacturing automobile engine piston rings, the inside diameter of the rings is a critical quality characteristic. Given the process average diameter is 74mm, the process standard deviation of diameter is 0.01mm and the sample size is 5.
- How the control limits are determined?

5

Analysis of Patterns

- Types of patterns:
 - Run (8 or more)
 - Cyclic behavior
- Western Electric Rules (Zone Rules):
 - One point outside 3σ control limits.
 - 2 / 3 consecutive points beyond a 2σ CL.
 - 4 / 5 consecutive points at $\geq 1\sigma$ from CL.
 - 8 consecutive points on one side of the CL.

6

The \bar{X} Control Chart

- When μ and σ are unknown...
- R = Range of the sample
- W = Relative range = R / σ
- $E(W) = d_2$; $\text{Stdev}(W) = d_3$
- What would be an estimator for σ ?
- What are the UCL and LCL?

7

Definitions

$$\bar{\bar{X}} = \frac{1}{m} \sum_{i=1}^m \bar{X}_i$$

\bar{X} control chart

$$\bar{R} = \frac{1}{m} \sum_{i=1}^m R_i$$

$$UCL = \bar{\bar{x}} + A_2 \bar{r}$$

$$CL = \bar{\bar{x}}$$

$$LCL = \bar{\bar{x}} - A_2 \bar{r}$$

R control chart

$$UCL = D_4 \bar{r}$$

$$CL = \bar{r}$$

$$LCL = D_3 \bar{r}$$

8

The R Control Chart

- What is a reasonable estimator for σ_R ?
- What are the corresponding CL's?
- Example: $n = 5; \bar{x} = 33.32, \bar{r} = 5.8$

9



P Chart

$$UCL = \bar{p} + 3\sqrt{\frac{\bar{p}(1-\bar{p})}{n}}$$

$$CL = \bar{p}$$

$$LCL = \bar{p} - 3\sqrt{\frac{\bar{p}(1-\bar{p})}{n}}$$

- where \bar{p} is the observed value of the average fraction defective

10



U Chart

$$UCL = \bar{u} + 3\sqrt{\frac{\bar{u}}{n}}$$

$$CL = \bar{u}$$

$$LCL = \bar{u} - 3\sqrt{\frac{\bar{u}}{n}}$$

- where \bar{u} is the observed value of the average fraction defective

11

Control Chart Performance

- ARL = Average Run Length

$$ARL = \frac{1}{p}$$

- p -- probability that any point exceeds control limits

12