
Year: 2012 Month: 4 Two new anchor lines (out of 4) set out when platform returned to lake center in April 2011 to replace one lost and one dragged to dock October2010 See figure to right for actual de 24 March 2012; platform move to lake center, 12-1:00m Nov11: Tightened electrical connections for Tw's in MUX box on 13Nov11 (most could be tightened 1/2 turn or more so this may have solved problem detected earlier) Explanded and the level data with model for period 20-27Nov11 after platform drifted to north side of dock (used actual evap and rain and modeled outflow from lake level and fitted rain yield for runoff to match final lake level on 2



 Lake level is mm above lower edge of dock metal frame (mm of water at #C based on pressure)

 Monthly rain (incl melt in gage):
 2.64
 inches
 2.12
 in. precip from Hamilin/Scranton NWS

22-Apr

32.26

28.80

Dock old deck upper surface (before replacement with new artificial wood decking) was at about +200 mm at SE corner but about +50-100mm at NW & NE corners)

201

77%

Precip from rain gage is underestimated during freezing conditions and appears late when air temperature rises above freezing. Lake level rise accurately reflects rain or the water equivalent of snow, plus runoff and snowmelt.

