

Tw12m sensor damage noted on 21Apr07 (animal bite through outer insulation near bottom); will need to replace it but currently it's working again







Lake level is mm above lower edge of dock metal frame (mm of water at 4°C based on pressure)

Monthly rain (incl melt in gage): 2.21 inches 2.47 in. (incl. winter frozen precip) from Avoca NWS Dock upper surface is at about +200 mm at SE corner but about +50-100mm at NW & NE corners)

mm

Precip from rain gage is underestimated during freezing conditions and appears late when air temperature rises above freezing. Lake level rise accurately reflects rain or the water equivalent of snow, plus runoff and snowmelt.





		mm Precip,	mm Precip,		mm
	date	AV	Lac	date	Precip, AV
accuweather (Avoca)	10-Jul	6.86	7.40	23-Jul	7.11
rain or water-equiv snow, mm	12-Jul	5.84	5.30	25-Jul	17.78
	14-Jul	7.87	8.40	29-Jul	5.84
	19-Jul	11.18	7.60		
	20-Jul	0.25	0.20		

Precip, Lac	date	mm Precip, AV	mm Precip, Lac	
6.80			-	
12.40			-	
6.30			-	
-			-	
-			-	

