

L. Lacawac Hourly avg Lake level, Lake level change/hr, Rain/hr TO LAKE CENTER 24Mar2012, to dock 3Nov12  
Lake level sensor (15psi) vent tube broken above water sensor dragged by "Superstorm Sandy" 29Oct2012; replaced 11Nov12 w/ 30psi sensor

